

Photo Report
Milford Mini Park
Programs, Services, and Activities

Finding: Milford Mini Park, located at 601 West Milford in Glendale California, was inspected by Disability Access Consultants, Inc., on August 13, 2007.



Alternative *
Rec:
(Where Available)

Full Rec: Any renovation or new construction that occurred after January 26, 1992, is subject to meet full code specifications for the California Building Code and ADAAG requirements. All recommendations in this report are based on ADAAG and CBC title 24 requirements. Consult with your design professional to determine which elements are affected by these requirements. It is recommended that Disability Access Consultants, Inc. is consulted for inspection of any new construction or renovation at the facility.

Citations: ADAAG 4.1.2; ADAAG 4.1.3; ADAAG 4.1.5; ADAAG 4.1.6
 Minimum Quantity: 1
 Maximum Quantity: 1
Minimum Estimated Cost: \$0.00
Maximum Estimated Cost: \$0.00
 Record Number: 944
 Priority:

Curbs, Curb Ramps, and Crosswalks

Finding: The slope of the curb ramp is greater than 8.33%. The slope at the top landing is greater than 2%. The slope of the side flares is greater than 10%. The transition at the bottom landing is abrupt. The concrete curb ramp does not provide a detectable warning surface which includes truncated domes.



Alternative *
Rec:
(Where Available)

Full Rec: Replace the curb ramp with a compliant curb ramp at least 48 inches in width that provides a slope no greater than 8.33%. Install a detectable warning surface which extends the full length and width of the concrete curb ramp and its side flares with truncated domes that contrast visually by either light on dark or dark on light which is an integral part of the concrete curb ramp. The truncated domes may be cast in place or stamped or of a prefabricated surface treatment (see CBC 1127B.5.8).

Curb Ramp at the Corner of Milford and Kenliworth
 Citations: CBC 1127B.5.3; ADAAG 4.7.2 & 4.29
 Minimum Quantity: 1
 Maximum Quantity: 1
Minimum Estimated Cost: \$1,033.00
Maximum Estimated Cost: \$1,033.00
 Record Number: 945
 Priority:

Milford Mini Park

Curbs, Curb Ramps, and Crosswalks

Finding: The slope of the curb ramp is greater than 8.33%. The top landing is grass, preventing access to individuals with mobility impairments. The bottom landing is woodchips, preventing access to individuals with mobility impairments. The concrete curb ramp does not provide a detectable warning surface which includes truncated domes.

Alternative *
Rec:
(Where Available)



Curb Ramp at the Play Equipment

Citations: CBC 1127B.5.3; ADAAG 4.7.2 & 4.29

Full Rec: Replace the curb ramp with a compliant curb ramp at least 48 inches in width that provides a slope no greater than 8.33%. Install a detectable warning surface which extends the full length and width of the concrete curb ramp and its side flares with truncated domes that contrast visually by either light on dark or dark on light which is an integral part of the concrete curb ramp. The truncated domes may be cast in place or stamped or of a prefabricated surface treatment (see CBC 1127B.5.8).

Minimum Quantity:	1
Maximum Quantity:	1
Minimum Estimated Cost:	\$1,033.00
Maximum Estimated Cost:	\$1,033.00
Record Number:	949
Priority:	

Path of Travel

Finding: There is an accessible route from the public right of way to the accessible entrance of the facility.

Alternative *
Rec:
(Where Available)



Accessible Route from the Public Right of Way

Full Rec: Post directional signage. Make certain to post signage indicating the direction to accessible building entrances at every major junction along the accessible route. Signs shall include the International Symbol of Accessibility.

Citations: CBC 1114B.1.2; CBC 1117B.5.7; CBC 1127B.3; ADAAG 4.1.2(7); ADAAG 4.3.2; ADAAG 4.14.1	
Minimum Quantity:	1
Maximum Quantity:	1
Minimum Estimated Cost:	\$107.00
Maximum Estimated Cost:	\$107.00
Record Number:	950
Priority:	


Milford Mini Park

Visual and Audible Communications

Finding: There is no directional signage to the accessible entrance from the public right of way or other common use areas.

Alternative *
Rec:
(Where Available)

Full Rec: Install directional signage to each common area complying with CBC 1117B.5 and ADAAG 4.30.



Directional Signage

Citations: CBC 1117B.5; ADAAG 4.30

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$58.00
Maximum Estimated Cost:	\$58.00

Record Number: 951

Priority:

Commons/Lunch Area

Finding: There is no accessible route to the picnic tables in the outdoor dining area. The surface around the outdoor dining area is grass, preventing access of individuals with mobility impairments.

Alternative *
Rec:
(Where Available)

Full Rec: Install a 48-inch wide path to the picnic tables in the outdoor dining area that provides a smooth, stable, firm and slip resistant surface. Provide a maneuvering space sufficient to provide a 60-inch diameter turning radius adjacent to at least one of the picnic tables in the outdoor dining area.



Outdoor Dining Area

Citations: ADAAG 5.8; ADAAG A4.2.5; ADAAG A4.2.6

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$1,440.00
Maximum Estimated Cost:	\$1,440.00

Record Number: 947

Priority:

**Milford Mini Park
Commons/Lunch Area**

Finding: The knee space at the tables in the outdoor dining area is less than 19 inches deep.

Alternative *
Rec:
(Where Available)



Outdoor Dining Area

Full Rec: Modify or replace one of the tables in the outdoor dining area to provide knee clearance of at least 27 inches in height, 30 inches in width and 19 inches in depth (see CBC 1122B.3, ADAAG 4.32.2 and ADAAG Figure 45). The table top height shall not exceed 34 inches above the finished floor.

Citations: CBC 1122B.3; ADAAG 4.32.2; ADAAG 4.32.5(2)

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$174.00
Maximum Estimated Cost:	\$174.00

Record Number: 948

Priority:

Playground and Outdoor Sports Areas

Finding: The path of travel to the play area consists of grass, making the area nonaccessible to individuals with mobility impairments. The surface beneath the play area is wood chips, making the area nonaccessible to individuals with mobility impairments.

Alternative *
Rec:
(Where Available)



Play Equipment

Full Rec: Provide an accessible route to the play area (CBC 1104B.1.2 and ADAAG 4.3.2). The minimum width of the path of travel is 48 inches that provides a firm, stable and slip resistant surface. Provide a maneuvering space with an accessible resilient surface beneath the play components and adjacent to the play components where technically feasible. An adequate maneuvering space has an accessible surface and is not less than 60 inches by 60 inches where an individual with a mobility impairment can be a part of the activities provided at the play components.

Citations: CBC 1104B.1.2; CBC 1124B.1; ADAAG 4.3.2; ADAAG 4.5

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$360.00
Maximum Estimated Cost:	\$360.00

Record Number: 946

Priority: