

Photo Report
Wilson Mini Park
Programs, Services, and Activities

Finding: The Wilson Mini Park, located at 1101 Wilson Avenue in Glendale California, was inspected by Disability Access Consultants, Inc., on August 13, 2007.



Alternative *
Rec:
(Where Available)

Full Rec: Any renovation or new construction that occurred after January 26, 1992, is subject to meet full code specifications for the California Building Code and ADAAG requirements. All recommendations in this report are based on ADAAG and CBC title 24 requirements. Consult with your design professional to determine which elements are affected by these requirements. It is recommended that Disability Access Consultants, Inc. is consulted for inspection of any new construction or renovation at the facility.

Citations: ADAAG 4.1.2; ADAAG 4.1.3; ADAAG 4.1.5; ADAAG 4.1.6
 Minimum Quantity: 1
 Maximum Quantity: 1
Minimum Estimated Cost: \$0.00
Maximum Estimated Cost: \$0.00
 Record Number: 1743
 Priority:

Curbs, Curb Ramps, and Crosswalks

Finding: The slope of the curb ramp is greater than 8.33%. The slope at the bottom landing is greater than 2%. The slope at the top landing is greater than 2%. The slope of the side flares is greater than 10%. The concrete curb ramp does not provide a detectable warning surface which includes truncated domes.



Curb Ramp at the Corner of Wilson and Adams

Alternative *
Rec:
(Where Available)

Full Rec: Replace the curb ramp with a compliant curb ramp at least 48 inches in width that provides a slope no greater than 8.33%. Install a detectable warning surface which extends the full length and width of the concrete curb ramp and its side flares with truncated domes that contrast visually by either light on dark or dark on light which is an integral part of the concrete curb ramp. The truncated domes may be cast in place or stamped or of a prefabricated surface treatment (see CBC 1127B.5.8).

Citations: CBC 1127B.5.3; ADAAG 4.7.2 & 4.29
 Minimum Quantity: 1
 Maximum Quantity: 1
Minimum Estimated Cost: \$1,033.00
Maximum Estimated Cost: \$1,033.00
 Record Number: 1744
 Priority:

Wilson Mini Park

Path of Travel

Finding: There is an accessible route from the public right of way to the accessible entrance of the facility.



Accessible Route from the Public Right of Way

Alternative *

Rec:
(Where Available)

Full Rec: Post directional signage. Make certain to post signage indicating the direction to accessible building entrances at every major junction along the accessible route. Signs shall include the International Symbol of Accessibility.

Citations: CBC 1114B.1.2; CBC 1117B.5.7; CBC 1127B.3; ADAAG 4.1.2(7); ADAAG 4.3.2; ADAAG 4.14.1

Minimum Quantity: 1

Maximum Quantity: 1

Minimum Estimated Cost: \$107.00

Maximum Estimated Cost: \$107.00

Record Number: 1749

Priority:

Visual and Audible Communications

Finding: There is no directional signage to the accessible entrance from the public right of way or other common use areas.



Alternative *

Rec:
(Where Available)

Full Rec: Install directional signage to each common area complying with CBC 1117B.5 and ADAAG 4.30.

Directional Signage

Citations: CBC 1117B.5; ADAAG 4.30

Minimum Quantity: 1

Maximum Quantity: 1

Minimum Estimated Cost: \$58.00

Maximum Estimated Cost: \$58.00

Record Number: 1750

Priority:

**Wilson Mini Park
Drinking Fountains**

Finding: There is one drinking fountain on primary paths of travel.



Alternative *
Rec:
(Where Available)

Full Rec: Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirement. Fountains not located in alcoves need side rails or wing walls on both sides.

Citations: CBC 1117B.1; ADAAG 4.15

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$0.00
Maximum Estimated Cost:	\$0.00

Record Number: 1747

Priority:

Drinking Fountains

Finding: The drinking fountain is not a "high-low" design.



Alternative *
Rec:
(Where Available)

Full Rec: Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain.

Citations: CBC 1117B.1; ADAAG 4.15

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$2,216.00
Maximum Estimated Cost:	\$2,216.00

Record Number: 1748

Priority:

Drinking Fountain Next to the Play Equipment

**Wilson Mini Park
Commons/Lunch Area**

Finding: The tables in the outdoor dining area are nonaccessible by design.

Alternative *
Rec:
(Where Available)



Outdoor Dining Area

Full Rec: Modify or replace one of the tables in the outdoor dining area to provide knee clearance of at least 27 inches in height, 30 inches in width and 19 inches in depth (see CBC 1122B.3, ADAAG 4.32.2 and ADAAG Figure 45). The table top height shall not exceed 34 inches above the finished floor.

Citations: CBC 1122B.3; ADAAG 4.32.2; ADAAG 4.32.5(2)

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$174.00
Maximum Estimated Cost:	\$174.00

Record Number: 1746

Priority:

Playground and Outdoor Sports Areas

Finding: The surface beneath the play equipment is wood chips, making the area nonaccessible to individuals with mobility impairments. There is a change in elevation greater than 1/2 inch at the entrance to the play equipment, due to the a lack of fill.

Alternative *
Rec:
(Where Available)



Play Equipment

Full Rec: The play area should be made an accessible play area for the facility. Provide a maneuvering space with an accessible resilient surface beneath the play components and adjacent to the play components where technically feasible. An adequate maneuvering space has an accessible surface and is not less than 60 inches by 60 inches where an individual with a mobility impairment can be a part of the activities provided at the play components.

Citations: CBC 1118B.3; ADAAG 4.5; ADAAG A4.5.1)

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$300.00
Maximum Estimated Cost:	\$300.00

Record Number: 1745

Priority: