

**Photo Report**  
**Windsor Mini Park**  
**Programs, Services, and Activities**

**Finding:** The Windsor Mini Park, located at 1300 East Windsor in Glendale California, was inspected by Disability Access Consultants, Inc., on June 12, 2007.



**Alternative \***  
**Rec:**  
**(Where Available)**

**Full Rec:** Any renovation or new construction that occurred after January 26, 1992, is subject to meet full code specifications for the California Building Code and ADAAG requirements. All recommendations in this report are based on ADAAG and CBC title 24 requirements. Consult with your design professional to determine which elements are affected by these requirements. It is recommended that Disability Access Consultants, Inc. is consulted for inspection of any new construction or renovation at the facility.

Citations: ADAAG 4.1.2; ADAAG 4.1.3; ADAAG 4.1.5; ADAAG 4.1.6  
 Minimum Quantity: 1  
 Maximum Quantity: 1  
**Minimum Estimated Cost:** \$0.00  
**Maximum Estimated Cost:** \$0.00  
 Record Number: 1751  
 Priority:

**Curbs, Curb Ramps, and Crosswalks**

**Finding:** The width of the curb-cut ramp is less than 48 inches. The slope at the bottom landing is greater than 2%. The concrete curb ramp does not provide a detectable warning surface which includes truncated domes.



**Alternative \***  
**Rec:**  
**(Where Available)**

**Full Rec:** Replace the curb ramp with a compliant curb ramp at least 48 inches in width that provides a slope no greater than 8.33%. Install a detectable warning surface which extends the full length and width of the concrete curb ramp and its side flares with truncated domes that contrast visually by either light on dark or dark on light which is an integral part of the concrete curb ramp. The truncated domes may be cast in place or stamped or of a prefabricated surface treatment (see CBC 1127B.5.8).

**Curb Ramp at the Entrance to the Park**  
 Citations: CBC 1127B.5.3; ADAAG 4.7.2 & 4.29  
 Minimum Quantity: 1  
 Maximum Quantity: 1  
**Minimum Estimated Cost:** \$1,033.00  
**Maximum Estimated Cost:** \$1,033.00  
 Record Number: 1752  
 Priority:

## Windsor Mini Park

### Path of Travel

**Finding:** There is an accessible route from the public right of way to the accessible entrance of the facility.



**Accessible Route from the Public Right of Way**

Citations: CBC 1114B.1.2; CBC 1117B.5.7; CBC 1127B.3; ADAAG 4.1.2(7); ADAAG 4.3.2; ADAAG 4.14.1

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	\$107.00
<b>Maximum Estimated Cost:</b>	\$0.00

Record Number: 1757

Priority:

#### Alternative \*

**Rec:**  
**(Where Available)**

**Full Rec:** Post directional signage. Make certain to post signage indicating the direction to accessible building entrances at every major junction along the accessible route. Signs shall include the International Symbol of Accessibility.

### Visual and Audible Communications

**Finding:** There is no directional signage to the accessible entrance from the public right of way or other common use areas.



**Directional Signage**

Citations: CBC 1117B.5; ADAAG 4.30

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	\$58.00
<b>Maximum Estimated Cost:</b>	\$58.00

Record Number: 1758

Priority:

#### Alternative \*

**Rec:**  
**(Where Available)**

**Full Rec:** Install directional signage to each common area complying with CBC 1117B.5 and ADAAG 4.30.

**Windsor Mini Park  
Drinking Fountains**

**Finding:** There is one drinking fountain on primary paths of travel.



**Alternative \***  
**Rec:**  
**(Where Available)**

**Full Rec:** Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirement. Fountains not located in alcoves need side rails or wing walls on both sides.

Citations: CBC 1117B.1; ADAAG 4.15

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	<b>\$0.00</b>
<b>Maximum Estimated Cost:</b>	<b>\$0.00</b>

Record Number: 1755

Priority:

**Drinking Fountains**

**Finding:** The leading edge of the drinking fountain is more than 4 inches from the wall and greater than 27 inches from the floor and protrudes into the primary path of travel.



**Alternative \***  
**Rec:**  
**(Where Available)**

**Full Rec:** Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a side rail or wing wall next to each side of the fountain.

***Drinking Fountain at the Outdoor Dining Area***

Citations: CBC 1117B.1; ADAAG 4.15

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	<b>\$2,216.00</b>
<b>Maximum Estimated Cost:</b>	<b>\$2,216.00</b>

Record Number: 1756

Priority:

**Windsor Mini Park  
Commons/Lunch Area**

**Finding:** The tables at the outdoor dining area are nonaccessible by design.

**Alternative \***  
**Rec:**  
**(Where Available)**



**Outdoor Dining Area**

**Full Rec:** Modify or replace one of the tables in the outdoor dining area to provide knee clearance of at least 27 inches in height, 30 inches in width and 19 inches in depth (see CBC 1122B.3, ADAAG 4.32.2 and ADAAG Figure 45). The table top height shall not exceed 34 inches above the finished floor.

Citations: CBC 1122B.3; ADAAG 4.32.2; ADAAG 4.32.5(2)

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	\$174.00
<b>Maximum Estimated Cost:</b>	\$174.00

Record Number: 1753

Priority:

**Playground and Outdoor Sports Areas**

**Finding:** There are slopes greater than 6.33% along the path of travel to the play equipment. The surface beneath the play area is wood chips, making the area nonaccessible to individuals with mobility impairments.

**Alternative \***  
**Rec:**  
**(Where Available)**



**Play Equipment**

**Full Rec:** Provide an accessible route to the play area (CBC 1104B.1.2 and ADAAG 4.3.2). The minimum width of the path of travel is 48 inches with 60 inch by 60 inch passing spaces provided every 200 feet and shall not exceed a slope greater than 6.33%. Provide a maneuvering space with an accessible resilient surface beneath the play components and adjacent to the play components where technically feasible. An adequate maneuvering space has an accessible surface and is not less than 60 inches by 60 inches where an individual with a mobility impairment can be a part of the activities provided at the play components.

Citations: CBC 1104B.1.2; CBC 1124B.1; ADAAG 4.3.2; ADAAG 4.5

Minimum Quantity:	1
Maximum Quantity	1
<b>Minimum Estimated Cost:</b>	\$360.00
<b>Maximum Estimated Cost:</b>	\$360.00

Record Number: 1754

Priority: