

Accessibility Survey

Americans with Disabilities Act And Title 24 of the California Building Code



City of Glendale

Downtown Parking Lot #11

122 E Colorado Street

Inspected January 2008

Prepared By

Disability Access Consultants, Inc.
(800) 743-7067



Facility Name: Downtown Parking Lot #11

Programs, Services, and Activities

Finding: Parking Lot # 11 is located at 122 East Colorado Street in Glendale, California. The parking lot was inspected by Disability Access Consultants, Inc., on January 15, 2008.



**Alternative Rec:
(Where Available)**

Full Rec:

Citations:

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$0.00
Maximum Estimated Cost:	\$0.00
Record Number::	101
Priority:	

Parking

Finding: There are no accessible parking spaces out of 66 parking spaces which does not meet the minimum number for compliance.



Accessible Parking

**Alternative * Rec:
(Where Available)**

Full Rec: Three (3) out of 66 total parking spaces are required to be designated exclusively for accessible parking. Create three accessible spaces, each measuring at least 108 inches wide and 216 inches long. Designate one parking space as "van-accessible". The van-accessible space shall provide an access aisle measuring at least 96 inches wide on the passenger side the space. The two additional parking spaces shall each provide an access aisle measuring at least 60 inches wide, that may be shared. Add the words NO PARKING in 12 inch high white letters at the entrance to each accessible parking access aisle.


Citations: CBC 1129B; ADAAG 4.6; ADAAG A4.6

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$270.00
Maximum Estimated Cost:	\$270.00
Record Number::	102
Priority:	

Facility Name: Downtown Parking Lot #11

Parking

Finding: There is no warning signage posted at the entrance from East Colorado Street regarding unauthorized use of accessible parking spaces in the parking lot.



Accessible Parking

Citations: CBC 1129B.5; ADAAG 4.6.4 CVC 22511.8(a)(d)

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$150.00
Maximum Estimated Cost:	\$150.00
Record Number::	103
Priority:	

Alternative *
Rec:
(Where Available)

Full Rec: Post a sign in a conspicuous place at the entrance of the parking lot, or immediately adjacent to and visible from each accessible space. The warning sign shall measure at least 17 inches by 22 inches in size and consist of lettering at least 1 inch in height that states the following; "Unauthorized vehicles parked in designated accessible spaces not displaying distinguishing placards or license plates issued for persons with disabilities may be towed away at owner's expense. Towed vehicles may be reclaimed at _____ or by telephoning ____ ." Fill in the blank spaces with appropriate information as a permanent part of the sign and be sure to add the CVC 22511.8(a)(d) to the sign.

Path of Travel

Finding: There is no accessible route from the public right of way to the parking lot or to the accessible parking space.



Accessible Route from the Public Right of Way

Citations: CBC 1114B.1.2; CBC 1117B.5.7; CBC 1127B.3; ADAAG 4.1.2(7); ADAAG 4.3.2; ADAAG 4.14.1

Minimum Quantity:	1
Maximum Quantity	1
Minimum Estimated Cost:	\$107.00
Maximum Estimated Cost:	\$0.00
Record Number::	104
Priority:	

Alternative *
Rec:
(Where Available)

Full Rec: Provide at least one accessible route from the public right of way to the parking lot and to the accessible parking spaces. Make certain to post signage indicating the direction of the accessible route to the public right of way. Signs shall include the International Symbol of Accessibility.